

## Tabela de Conversão de Polegadas em Milímetros

Pol.	mm	Pol.	mm.	Pol.	mm	Pol.	mm
1/32	0,794	29/32	23,02	125/32	45,24	3 5/8	92,08
1/16	1,588	15/16	23,81	113/16	46,04	3 3/4	95,25
3/32	2,380	31/32	24,61	127/32	46,83	3 7/8	98,43
1/8	3,180	1	25,40	17/8	47,62	4	101,60
5/32	3,970	11/32	26,19	129/32	48,42	4 1/4	107,95
3/16	4,760	11/16	26,99	115/16	49,21	4 1/2	114,30
7/32	5,560	13/32	27,78	131/32	50,00	4 3/4	120,65
1/4	6,350	11/8	28,57	2	50,80	5	127,00
9/32	7,140	15/32	29,37	21/16	52,39	5 1/2	139,70
5/16	7,940	13/16	30,16	21/8	53,97	6	152,40
11/32	8,730	17/32	30,95	23/16	55,56	6 1/2	165,10
3/8	9,530	11/4	31,75	21/4	57,15	7	177,80
13/32	10,320	19/32	32,54	25/16	58,74	8	203,20
7/16	11,110	15/16	33,34	23/8	60,32	9	228,60
15/32	11,910	111/32	34,13	27/16	61,91	10	254,00
1/2	12,700	13/8	34,92	21/2	63,50	11	279,40
17/32	13,490	113/32	35,72	29/16	65,09	12	304,80
9/16	14,290	17/16	36,51	25/8	66,67	13	330,20
19/32	15,080	115/32	37,30	211/16	68,26	14	355,60
5/8	15,875	11/2	38,10	23/4	69,85	15	381,00
21/32	16,670	117/32	38,89	213/162	71,44	16	406,40
11/16	17,460	19/16	39,69	27/8	73,02	17	431,80
23/32	18,260	119/32	40,48	215/16	74,61	18	457,80
3/4	19,050	15/8	41,27	3	76,20	19	482,60
25/32	19,840	121/32	42,07	31/8	79,38	20	508,00
13/16	20,640	111/16	42,86	31/4	82,55	21	533,40
27/32	21,430	123/32	43,65	33/8	85,73	22	558,80
7/8	22,220	13/4	44,45	31/2	88,90	23	584,20